

Αξιολόγηση του USB Uni-T UT658

UNI-T · EAN 6935750565803

Machine translation from Polski. In case of doubt the manufacturer's original document prevails.

USB SOCKET TESTER UNI-T UT658

MIE0291

USER MANUAL

User Manual

SAFETY ISSUES

Before use, please read the user manual carefully and keep it for future reference. The following instructions contain advice and tips for the proper use of this device. Pay attention to the safety information when operating this device. The meter should only be used in accordance with the instructions below. 1. The device should be protected from water and moisture, even during storage. Do not use or store the device in extreme temperatures. The device should not be stored in temperatures and humidity exceeding the allowed range. Do not use or store the meter in a location with a strong magnetic field. 2. The device should be protected from direct sunlight and heat sources. Do not expose the device to falls. 3. The meter is not a toy; it should be kept out of reach of children. 4. The device should be cleaned only with a soft, slightly damp cloth. Do not use detergents to clean this device. 5. Before measuring, check if the device's casing is damaged. Do not use this device if it is damaged. Self-repair/disassembly of the equipment is prohibited. Self-disassembly may affect measurement accuracy. The device does not have parts that can be repaired by the user. In case of damage, contact an authorized service center for inspection/repair. 6. The manufacturer is not responsible for accidents, injuries, or damages caused by improper use of the device and non-compliance with the user manual.

PACKAGE CONTENTS

Check the contents of the meter's packaging - ensure that the items listed below are in the box and that they are not damaged:

- meter
- user manual

PRODUCT DESCRIPTION

HOUSING

1. USB Port 4

2. Function Button

3. Display

4. USB Socket

1 2 3

DEVICE OPERATION

To start using the device, you need to:

Insert the meter's USB port (1) into the USB socket of the external device. The display will show information about the current and voltage in the USB socket. If the output voltage is higher than the allowable charging voltage range, stop using the device. If the voltage is higher than 5.30 V or lower than 4.70 V, the display will show an indicator indicating a non-standard measurement result. When the voltage is within the norm, connect the external device to the input socket of the tester (4). Press the function button to display the last measurement (the device saves the last 10 measurements). Press and hold for about 1.5 seconds to delete the selected measurement. Note: the user can change cables while taking measurements.

CLEANING

The device should be cleaned only with a soft, slightly damp cloth. Do not use chemicals or detergents to clean the device.

USER MANUAL

SPECIFICATION

- Input Voltage: 3.0 V – 9.0 V
- Direct Current: 0 – 3.0 A
- Charging Capacity: 0 – 9999 mAh
- Memory: 10 last results

This document is a translation of the original user manual created by the manufacturer.

Detailed information about the distributor/manufacturer's warranty conditions is available at the website <https://serwis.innpro.pl/gwarancja>

The product should be regularly maintained (cleaned) by the user or through specialized service points at the user's cost and responsibility. If there is no information about necessary maintenance or service actions in the user manual, the user should regularly, at least once a week, assess the physical condition of the product against that of a physically new product. If any deviation is detected or noted, urgent maintenance (cleaning) or service steps should be taken. Failure to properly maintain (clean) and respond when a deviation is detected may lead to permanent damage to the product. The guarantor is not responsible for damages resulting from neglect.

Warnings and Safety Information

All information regarding operation and use can be found in the user manual or on the product label. Before starting to use the products, familiarize yourself with its content and follow the instructions contained therein. Also, review the following information before use:

User Safety

Use measuring tools according to their intended purpose.

Do not use measuring tools for tasks they were not designed for, to avoid damage or incorrect measurement results. Always ensure that the tool is in good technical condition before use. Damaged tools, such as cracked housings or broken displays, can lead to incorrect measurements or accident risks. Regularly calibrate measuring tools to ensure their accuracy and reliability of measurements. Incorrectly calibrated devices can lead to erroneous results. Precautions Use appropriate eye protection, especially when working with measuring tools that may emit radiation. Keep measuring tools away from children and untrained individuals to prevent accidental damage or misuse. Avoid using measuring tools in extreme temperature or humidity conditions, or in an atmosphere with a high concentration of dust, which may affect their accuracy and functionality. When working with measuring tools, exercise caution to avoid damaging delicate measuring components (e.g., sensors, probes). Safe Use Always ensure that the measuring tool is properly set up and secured to avoid measurement errors or damage. Use measuring tools only in designated areas that provide adequate stability and minimize the risk of accidents, such as slippery or uneven surfaces. Never take measurements on live components or in conditions that may pose a safety hazard. Operating Guidelines in Appropriate Conditions Store measuring tools in a dry, cool place, away from moisture and direct sunlight, which may damage the devices or affect their accuracy. When using measuring tools, ensure they are well seated and not exposed to shocks or impacts that may lead to damage. Avoid using measuring tools in places with extreme conditions, such as heavy vibrations, hot surfaces, dust, or moisture, unless the tool is designed for such conditions by the manufacturer. Maintenance Instructions Regularly check the condition of measuring tools, especially measuring components (e.g., sensors, probes, displays) and batteries. Follow the cleaning instructions provided by the manufacturer. Use appropriate cleaning materials (e.g., soft cloths) to avoid damaging delicate components. Regularly perform calibration of measuring tools, according to the manufacturer's recommendations, to maintain measurement accuracy. Safe Disposal Used or damaged measuring tools should be disposed of in accordance with applicable environmental protection and electronic recycling regulations. Do not throw measuring tools

in regular waste containers, as they may contain environmentally harmful components. Contact local authorities or recycling companies for information on proper disposal of used measuring tools.

Declaration of Conformity The products have been designed in accordance with the safety requirements specified in Regulation (EU) 2023/988 on the general safety of products, ensuring their compliance with applicable safety and health protection standards for users.

Environmental Protection Waste electrical and electronic equipment marked in accordance with the European Union directive must not be placed together with other municipal waste. It is subject to selective collection and recycling at designated points. By ensuring its proper disposal, you prevent potential negative consequences for the natural environment and human health. The collection system for waste equipment complies with locally applicable environmental protection regulations regarding waste disposal. Detailed information on this can be obtained from the municipal office, cleaning facility, or the store where the product was purchased. The product meets the requirements of the so-called New Approach directives of the European Union (EU) concerning issues related to user safety, health protection, and environmental protection, specifying hazards that should be detected and eliminated.

Importer: INNPRO Robert Błędowski sp. z o.o. Rudzka 65c 44-200 Rybnik, Poland tel. +48 533 234 303 hurt@innpro.pl www.innpro.pl Manufacturer: Uni-Trend Technology (China) Co., Ltd. Industrial North 1st Road, Songshan Lake Park, Dongguan City 6523808 Dongguan City, China info@uni-trend.com EU Representative: UNI-TREND TECHNOLOGY EU GMBH Affinger Strasse 12 86167 Augsburg, Germany info@amz-lab.de