


HUANUO

Desk Monitor Arm



HNCM9

EN IMPORTANT SAFETY INFORMATION

⚠ DANGER: Please carefully read all instructions before attempting installation. If you Do not understand the instructions or have any questions or concerns, please contact us.

⚠ CAUTION: Avoid the risk of personal injury and property damage!

⚠ WARNING: All fasteners must be firmly tightened!


- Before starting assembly, verify that all parts and hardware are included and undamaged. Do not use damaged or defective items. If you require replacements, please contact us.
- This product contains small parts that may pose a choking hazard.
- Do not use this product for any purpose that is not explicitly specified in this manual. Do not exceed the maximum weight capacity. We are not liable for damage or injury caused by incorrect assembly, improper mounting, or inappropriate use.
- Use this mounting system only for its intended purpose as described in these instructions. Do not use attachments not recommended by the manufacturer.

SAVE THESE INSTRUCTIONS.



VESA

75 x 75mm (3 x 3")
100 x 100mm (3.9 x 3.9")



Rotation
+180°/-180°



Swivel
+90°/-90°



Tilt
+45°/-45°



&



3/8-12/25"
(10-12mm)



+



&




3/8" (10mm)



M5 x 14mm

f x 3



M8 x 10mm

g x 2



h x 1



M10

k x 1



l x 1



1/8" (3mm)

o1 x 1




3/16" (5mm)

o2 x 1



1/4" (6mm)

o3 x 1



M4 x 12mm

q x 4



M4 x 30mm

r x 4






M4

s x 4






1-800-556-0533 (US/CA) Mon-Fri 8am - 8pm (CST) |
44-808-196-3874 (UK) Mon-Fri 2pm - 10pm (UTC) | ✉ support@huanuo.com
03-4446-2735 10:00 - 17:00 (平日のみ)







2A Option A

C-Clamp Mounting





2 Height Options














⚠ The C-clamp should contact the desk and the locking knob should be secured vertically against the bottom of the desk.

 If your desktop does not fit properly, you may be able to use a wood board or block as a spacer.





2B Option B






⚠ Fully tighten to secure the locking plate to the bottom of the desk.

3





⚠ Fully tighten the bolt.







If the connector is not level, use the monitor plate to level, then remove the monitor plate.

4





- ⚠ • The depth of the bottom holes may be different from the top holes.
- Do not turn the bolt past the bottom of the hole.
- If the bolt is too short, it may not adequately support the monitor.
- If the bolt is too long, it could damage the monitor.
- At least 4–5 turns into the threading is required.

Choose the bolt and spacer configuration that fits your monitor type.









For Flat Back Monitor



OR

For Curved Back Monitor






5



Slightly turn the tilt bolt counterclockwise, adjust, and then turn it clockwise to hold the monitor in position.



3/16" (5mm)

02 x 1










1/8" (3mm)

o1 x1



3/8" (10mm)





7



Do not position or swivel the monitor beyond the back edge of the desktop. Doing so may cause the unit to tip over and fall.

